Storm Damage Report (updated on 18.03.2023 till 09:00 P.M.)																	
Date of occurrence	District	Rev. Circle	Name of Village affected	No. of Village affected	Total Population affected	Partially				Any other Institutions		Damage	Other loss (Livestock, Road	Ex-Gratia distributed	Time	GPS Co-	Remarks
						Kutcha	Pucca	Kutcha	Pucca	affected			Communicatio			ordinates	
17-03-2023	Lakhimpur	North Lakhimpur	North Lakhimpur R.C.: Japisajia	1	-	-	-	-	-	-	-	-	-	-	-	-	APDCL Damage: 1. PSC Pole (7.5) = 6 Nos 2. Conductor-3.8 km. (under North Lakhimpur ED)
18-03-2022	Dima Haso	New Sangbar	New Sangbar R.C: New Tumbung, Rongmongve, Green Market, Umrangso 3 Kilo, Dongjen Raji, Hebron, Umrangso Lakeside, V. Varplak, Silum, Dima Hading. Sibraikro Raji. Haplai Raji, Luapui,	13	U/A	U/A	U/A	U/A	U/A	U/A	Nil	U/A	U/A	-	-	-	33KV line of Umrangso Electrical Division is severely damaged. Power supply is hampered. Other damages are under Assessment
Total				14	-	-	-	-	-	-	-	-	-	-	-	-	-