Storm Damage Report (updated on 21.06.2023 till 10.00 P.M.)																	
	District	Rev. Circle	Name of Village affected	No. of Village affected	Total Population affected	Partially Damaged Fully damaged					Crop	Other loss (Livestock,					
Date of occurrence						Kutcha Pucca				Institutions	Human life lost		Road Communication	Ex-Gratia distributed	Time	GPS Co- ordinates	Remarks
				arrected	arrected	Kutcna	Pucca	Kutcna	Pucca	affected		(in nect)	etc)				
20-06-2023	Kokrajhar	Kokrajhar	Kokrajhar R.C: Jamadarpara, Tengapara, Hadanpara, Khargaon, Harinaguri, Patharghat, Titaguri, Talguri, Majpara	9	1	1	0	0	0	0	0	0	-	-	-	-	PSC Pole (8.5Mts) = 15nos. Conductor LT = 1.707Km. Conductor HT = 0.52Km
21-06-2023	Kokrajhar	Bhawraguri, Gossaigaon	Bhawraguri R.C: Boalimari, Patialpara, Musalmanpara,Gongia FV Gossaigaon R.C: Gossaigaon Town, Nepalpara, Jajlaigaon, Dhauliguri No.2, Joyma, Ballamguri, No.1 Hudumkhata, Shyamaguri, No.1 Simultapu	13	0	0	0	0	0	0	0	0	-	-	-	-	Transformer -12 Nos PSC-7 Nos. ACSR Conductor-1.6 km
20.06.2023	Bongaigaon	Dangtol	Dangtol R.C:- Bidyapur (New Bongaigaon Rly Colony)	1	395	0	1	0	0	1	0	0	-	-	-	-	Vivekmands Vidyapith H.S. School's Building roof damaged (395 Students)
Total 23 396					396	1	1	0	0	1	0	0	-	-	-	-	-